

IMPORTANT SAFETY RECALL

Louisville Ladder Certain Type IA, Type I and Type II "D" Rung Fiberglass Extension Ladders

The fly section on the ladder may bind without locking.

The following Louisville/Davidson ladders are affected:

534-XX (24' – 40')	FE3224-E08	FE3232
578-XX (24' – 32')	FE3224-LO32	FE3232-E03
618-XX (24' and 28')	FE3228	FE3236
FE1724	FE3228-010002	FE3240
FE1728	FE3228-74037	L-3022-XXPT (24' – 32')
FE3224	FE3228-E03	L-3121-24
FE3224-E03	FE3228-E03E34	

(On the ladder, the "XX" will identify a particular model size).

**Only ladders with manufacture dates/date codes of
September 2007 and October 2007 are affected.**

Ladders manufactured during September 2007 and October 2007 but with two green dots near the bottom of the left side base rail have already been inspected or repaired and are not affected.



The model number can be located on the model number label on the left side rail of the ladder.



If your ladder is affected, STOP USING IT IMMEDIATELY, and call Louisville Ladder toll free at 1-800-660-4356 between 8:00 a.m. and 5:00 p.m., Eastern Time, Monday through Friday, or at www.louisvilleladder.com for information on how to inspect and receive compensation if necessary.